

Site 6 Field Work Update

Former Naval Station Treasure Island

June 2015 BCT Meeting Louie Cardinale, Navy Remedial Project Manager

6/17/2015

Overview



- Project Goals
- Site Description
- Field Work Status
- Field Work Photos
- Future Milestones
- Questions

Project Goals




- Look for any Radiological Contamination at Site 6 Due to Historical Activities or Current Environmental Restoration Efforts
- Achieve Unrestricted Free Release of Site 6
- Allow for Chemical Cleanup to Start

Site Description



- Former Fire Training School Area
 - Staging Area for Low-Level Radioactive Waste Bins From 2007 until 2014
- Former Parking and Storage/Salvage Area

Salvage Yards May Have Handled Scrap With Radium Markers or



Field Work Status




- Percent complete 80% Anticipate Completion by July 24, 2015
- Volume of Soil Excavated to Date 1,550 Cubic Yards
- So Far, One Low-level Radioactive Object Found
 - ➤ Marker ~ Size of a Quarter
 - > 1.4 mR/hr on Contact

Deck Marker Found

Field Work Status (continued)



- Removed Rock Containing Naturally Occurring Thorium
 - ➤ Rock Approximately the Size of a Golf Ball




Field Work Photos





Removing Roadbase Material – Former Parking and Storage Area



Collecting Soil Sample



Removing Rad Cleared Soil From Screening Pad

Field Work Photos (continued)





Application of SoilTac - Dust Control



Scanning of Truck Leaving Site



Removal of Soil and Dust Control



Cleaning Sample Equipment

Future Milestones



- Complete all Field Work July 24, 2015
- Draft, Final Status Survey Report November 2015

Questions



